

Report of Inspection/Test

Biennial Smoke Detector Sensitivity

February 23, 2010

Property

CTU - Utah
326 South State Street
Salt Lake City, UT 84104

Owner/Agent

CTU - Utah
326 South State Street
Salt Lake City, UT 84104





P.O. Box 741
Layton, UT 84041
Phone: (801) 544-7345
Fax: (801) 544-1411

Jack Bauer
(801)867-5309

Jack Bauer
(801)867-5309

Conducted by: Tony Almeida
Inspection Ref: 20720

Signatures

Inspector - Printed TONY ALMEIDA	Inspector - Signature 	Date 2/23/10 1:55 pm	I state that the information on this form is correct at the time and place of my inspection, and all equipment tested at this time was left in operational condition upon completion of this inspection except as noted.
Owner - Printed JACK BAUER	Owner - Signature 	Date 2/23/10 1:56 pm	I acknowledge this report has been reviewed with me. Except as noted, there have been no changes to the original approved system.
Owner - Defic - Printed JACK BAUER	Owner - Defic - Signature 	Date 2/23/10 1:57 pm	This acknowledges notification of deficiencies in the system. These deficiencies could endanger facility occupants. This acknowledgement is not an authorization to repair these deficiencies.

Device Summary

Device	Qty	Manufacturer Model	Quantity Tested	% of Total Tested	Quantity Failed
SMOKE DETECTORS	10	SILENT KNIGHT SD500	10	100%	0

Report of Inspection/Test

Biennial Smoke Detector Sensitivity
February 23, 2010



Property: CTU - Utah
Owner: CTU - Utah

Inspection Ref: 20720

Smoke Detector Sensitivity Test

Zone/ Address	Equip ID	Location/Description	Manufacturer	Allowed Sensitivity Range (%)	Measured Sensitivity (%)	Sensitivity	Condition	Alarm Test
33:001	01	SERVER ROOM SOUTHEAST	SILENT KNIGHT SD505AHS	0.88%-3.57%	1.75	Ok	Ok	Ok
33:002	02	SERVER ROOM SOUTHWEST	SILENT KNIGHT SD505AHS	0.88%-3.57%	1.86	Ok	Ok	Ok
33:003	03	SERVER ROOM NORTHEAST	SILENT KNIGHT SD505AHS	0.88%-3.57%	2.01	Ok	Ok	Ok
33:004	04	SERVER ROOM NORTHWEST	SILENT KNIGHT SD505AHS	0.88%-3.57%	1.47	Ok	Ok	Ok
33:015	05	SOUTH HALL BY ENTRY	SILENT KNIGHT SD505AHS	0.88%-3.57%	1.72	Ok	Ok	Ok
33:016	06	DATA ANALYSIS FLOOR EAST	SILENT KNIGHT SD505AHS	0.88%-3.57%	3.71	S	Ok	Ok
DETECTOR FAILED; REPLACED WITH NEW								
33:017	07	DATA ANALYSIS FLOOR WEST	SILENT KNIGHT SD505AHS	0.88%-3.57%	2.35	Ok	Ok	Ok
33:018	08	INTERROGATION ROOM 1	SILENT KNIGHT SD505AHS	0.88%-3.57%	2.29	Ok	Ok	Ok
33:019	09	MEDICAL DEPARTMENT	SILENT KNIGHT SD505AHS	0.88%-3.57%	1.42	Ok	Ok	Ok
33:020	10	ABOVE FACP	SILENT KNIGHT SD505AHS	0.88%-3.57%	2.87	Ok	Ok	Ok
Inspection Service Summary	Number of Smoke Detectors	10	S	Items serviced	1	0	0	
			X	Items requiring service	0	0	0	

Report of Inspection/Test

Biennial Smoke Detector Sensitivity
February 23, 2010

Property: CTU - Utah

Owner: CTU - Utah

Inspection Ref: 20720



Deficiency Summary

These items were deficient and do not meet the requirements of the applicable code at the time of the inspection. Items marked *Recommendation* are not required by the applicable code but are opportunities to improve the Life Safety of the property.

Smoke Detector Inspection/Test 33:016 06 DATA ANALYSIS FLOOR EAST

DETECTOR FAILED; REPLACED WITH NEW

S

Sensitivity Ok ?